	uesday, 09/f0/2007 2:55:16 PM nda Lacelle	Proc	ess Sheet	Es 4	SPL	it 2
-Customer Job Number	: CU-DAR001 Dart Helicopters Services : 35031 — 2		Drawing Name	: ARM		*
Estimate Number P.O. Number This Issue Prsht Rev. First Issue Previous Run Written By Checked & Appro	: MA : 09/10/2007 S.O. No. : MA : NC : MALL /MED F : 35031	4 EC	Part Number Drawing Number Project Number Drawing Revision Material Due Date	: D3560043 : D3560 REV C : N/A : C : N/A : 19/10/2007	Qty:	5 _10 Um: Each
Additional Produ						
Job Number:						
Seq. #:	Machine Or Operation:		Description :			
1.0	M6061T6B0500X05000	6061-T6	Bar .50" x 5.0"			
Comn	nent: Qty.: 1.3598 f(s)/Unit Total: 13.5 6061-T6 Bar 0.50" x 5.00" Batch: 3	5975 f(s)		36		
2.0	BAND SAW	BAND SA	AW		5. F.20	es (ie)
Comm	nent: BAND SAW				#111 ##11 18#1	-
	Cut blanks 15.500" long			Se :-	Lie 2-8	(-3)
3.0	HAAS1	HAAS CN	IC VERTICAL MACHINING	s#1		
Comm	1- Mill as per Folio FA695 Rev: 464 &	Dwg D3560	Rev: _C			
	2-C'sink 0.196" hole on manual mill as pe	r dwg D356	0			
	3-Deburr per dwg D3560			B6 0	7.110 20	(10)
4.0	QC2		PARTS AS THEY COME (OFF MACHINE		
	ent: INSPECT PARTS AS THEY COME OFF			·BG-	シチン	24 (10)
5.0	QC8	SECOND	CHECK			
Comm	ent: SECOND CHECK			- 1	27/	159



Date: Tuesday, 09/10/2007 2:55:16 PM User: Linda Lacelle **Process Sheet** Customer: CU-DAR001 Dart Helicopters Services Drawing Name: ARM Job Number: 35031 Part Number: D3560043 Job Number: Seq. #: Machine Or Operation: Description: 6.0 D35921 PLATE Comment: Qty.: 1.0000 Each(s)/Unit Total: 10.0000 Each(s) PLATE 7.0 LARGE FABRICATION RESOURCE 1 Comment: LARGE FABRICATION RESOURCE 1 1-Weld assembly as per dwg D3560 STEP: 1- clean material (buff bracket and bottom of arm with blue pad) 2- set up bracket and arm on jig 3- preheat bracket and arm with torch 4- clean before welding with brush 5- set up machine to 135 amps 6- weld across bottom and top ends 7- reheat with torch (_____) 8- on one side weld from bottom to top half way 9- same for other side (half way) 10- from half way point weld the rest of the first side (ease off pedal near end) 11- same for remaining side (ease off pedal near end) 8.0 QC5 INSPECTIVORK TO CURRENT STEP Comment: INSPECT WORK TO CURRENT STEP 9.0 VISUAL WELDING INSPECTION Comment: VISUAL WELDING INSPECTION 10.0 HAND FINISHING1 HAND FINISHING RESOURCE #1 Comment: HAND FINISHING RESOURCE #1 Chemical Conversion Coat as per QSI 005 4.1 11.0 QC3 INSPECT POWDER COAT/CHEMICAL CONVERSION Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION

01.4.08 7.0	3plit w/o from 10 on w/o #1 to 5 ox w/o #2	Sh	01-11-08	

Tuesday, 09/10/2007 2:55:16 PM Date: User: Linda Lacelle **Process Sheet** Customer: CU-DAR001 Dart Helicopters Services Drawing Name: ARM Job Number: 35031 Part Number: D3560043 Job Number: Seq. #: Machine Or Operation: Description: 12.0 D2808 Spacer Comment: Qty.: 1.0000 Each(s)/Unit Total: 10.0000 Each(s) Spacer batch: 13.0 SMALL FAB SMALL & MEDIUM FAB RESOURCE 1 Comment: SMALL & MEDIUM FAB RESOURCE 1 1-Press bushing in D3560 arm per dwg D3562 14.0 QC5 INSPECT WORK TO CURRENT STEP Comment: INSPECT WORK TO CURRENT STEP 15.0 PACKAGING PACKAGING RESOURCE #1 Comment: PACKAGING RESOURCE #1 Identify and Stock Location: ST 152 16.0 FINAL INSPECTION/W/O RELEASE Comment: FINAL INSPECTION/W/O RELEASE h D.11.15 Job Completion

5



DART AEROSPACE LTD	Work Order:	35031	
Description: Arm	Part Number:	D3560-3	
Inspection Dwg: D3560 Rev: 8		Page 1 of 1	

FIRST ARTICLE INSPECTION CHECKLIST

X First Article Prototype

Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
Ø0.507	+0.000/-0.001	.5065	~			
Ø0.196	+0.005/-0.001	-176	_			
Ø1.000	+0.010/-0.001	1-004	_			
Ø0.900	+0.010/-0.001	100				•
0.500	+/-0.010	499	~			
0.250	+/-0.010	751				
0.275	+/-0.010	- 275				
0.188	+/-0.010	-191				
2.000	+/-0.010	72.05	~			
1.750	+/-0.010	1. 755				-
1.702	+/-0.010	1.707				
Ø0.385 x 100°	+/-0.010 x 0.5°	- 3.8 cm	_			
0.250 Deep	+/-0.010	. 247	<u> </u>			

Measured by: 3C-	Audited by:	Toll	Prototype Approval:	N/A
Date: CFILD 25	Date:	07/10/23	Date:	N/A

Rev		Change	Revised by Approved
Α	07.01.17	New Issue Plo D3500-043	KI/II M
В	07.06.13	Dimensions updated per Dwg Rev B	KJ/JLM Z
			17 6




D3560-1 ARM (-041, SHOWN)
OR D3560-2 ARM (-042, OPPOSITE)

D3592-1 PLATE,
SEE DETAIL A

D3560-041 ARM WELDMENT (SHOWN), D3560-042 ARM WELDMENT (OPPOSITE) D3560-3 ARM (-043, SHOWN)
OR D3560-4 ARM (-044, OPPOSITE)

D3592-1 PLATE,
SEE DETAIL A

03560-043 ARM WELDMENT (SHOWN), 03560-044 ARM WELDMENT (OPPOSITE)



COPY

GENERAL NOTES

- 1) WELD PER QSI 004
- 2) FINISH: CHEMICAL CONVERSION COAT PER DART QSI 005 4.1
- 3) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
- 4) ALL DIMENSIONS ARE IN INCHES



	C		07.06.19	REMOVE POWE	DER COAT
	В		07.01.15	REDESIGN AS	WELDMENT, ADD POCKETS
	A		06.09.25	NEW ISSUE	
COPYTRICHT @ 2008 BY DART AEROSPACE LTD.	DESIGN	90	DRAWN BY	DART	DART AEROSPACE LTD.
THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE	CHECKED	#	APPROVED #	DRAWING NO. D3560	REV. C SHEET 1 OF 3
OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERUISSION FROM PART AEROSPACE LTD.	07.06	.19		ARM WELDMENT	SCALE 1:4

